

GUIDE FOR HOW TO CUT SOLID ALUMINUM MOSAIC

Tools you need prepare:

1. Angle grinder



2. Grinding wheel for cutting aluminum



3. Long steel ruler
4. Flowing water

Start to cut

1. Aluminum mosaic's color side toward the table, cut from the mesh side
2. Use long steel ruler to fix mosaic, no movement during cutting
3. Let water keep flowing on where need be cut, in order to cool down temperature during cutting
4. Start cutting using angle grinder, stably and quickly move the machine from the top down again and again until mosaic is cut off